

# Estate Inspection



**Area of Inspection: Goldsmid 2 – Clarendon Road, Livingstone Road, Sackville Road & Shirley Street**

**Date of Inspection: 29/5/2018**

**Housing Officer: Albert Donnelly**

**Attendees: none**

**Weather: slight rain**

Date	No	Block / Street	Description of problem	Action taken	Job number / reference	Re-inspection date
29-May		Clarendon Road	Boxes need clearing Tenant advised	Tenant spoken to		
29-May		Clarendon Road	Washing machine / rubbish ground floor	Letter to tenant		
29-May		Livingstone Road	No issues			
29-May		Livingstone Road	No issues			
29-May		Livingstone Road	No issues			
29-May		Livingstone Road	No issues			
29-May		Livingstone Road	No issues			
29-May		Livingstone Road	No issues			
29-May		Sackville Road	No issues			
29-May		Sackville Road	No issues			
29-May		Sackville Road	No issues			
29-May		Shirley Street	No issues			
29-May		Shirley Street	No issues			
29-May		Shirley Street	No issues			
29-May		Shirley Street	No issues			