

# Estate Inspection

**Area of Inspection: Goldsmid 3**

**Date of Inspection: 4/6/18**

**Housing Officer: Albert Donnelly**

**Attendees:**

**Weather conditions: Sunny**

No.	Block / Street	Description of problem	Action taken	Job number / reference	Re-inspection date
	Ellen Block immediately east of Clarendon House	Missing tiles Ellen Street block just to the east of Clarendon House tiles end of block	Mears emailed		
	Ellen Street	Mat	To be removed local procedures		
	Ellen Street	Mat	To be removed local procedures		
	Ellen Street	Fridge and plant pot	To be removed local procedures does have a note on stating it will be removed		
	1st Floor Ellen House	Baby carrier on stairwell of Ellen House first floor	To be removed local procedures does have a note on stating it will be removed		