

Estate Inspection

[Area of Inspection] Goldsmid 3

Date of Inspection: 4/12/17

Housing Officer: Albert Donnelly

Attendees:

Weather conditions: Fine

Date	No	Block / Street	Description of problem	Action taken	Job number / reference	Re-inspection date
4/12/17		Ellen Block	Tiles on end of block Ellen Street missing	Mears emailed		
4/12/17		Ellen Block immediately East of Clarendon House	Missing tiles - Ellen Street block just to the east of Clarendon House tiles end of block	Mears emailed		
4/12/17		Ellen Street	Mats left outside doors Ellen Street	To be removed local procedures		
4/12/17		Ellen Street	Mats left outside doors Ellen Street	To be removed local procedures		
4/12/17		Ellen Street	Mats left outside doors Ellen Street	To be removed local procedures		
4/12/17		Ellen Street	Mats left outside doors Ellen Street	To be removed local procedures		
4/12/17		Ellen Street	Mats left outside doors Ellen Street	To be removed local procedures		
4/12/17		Ellen Street	Ellen Street large pot outside	To be removed local procedures		
4/12/17		Ellen Street	Net curtains at entrance block nearest Ellen House	To be removed local procedures		
4/12/17		Ellen Street	Lamp outside	To be removed local procedures		
4/12/17		Ellen House	Floor 3 - Air freshener near lift entrance	To be removed local procedures		
4/12/17		Ellen House	Floor 7 - East side netting damaged hole on fire escape stairwell	Mears emailed		