

Estate Inspection



[Area of Inspection] Goldsmid 5

Date of Inspection: 18/12/2017

Housing Officer: Albert Doinnelly

Attendees:

Weather conditions: Fine

Date	No	Block / Street	Description of problem	Action taken /Sent to	Job number / reference	Re-inspection date
18/12/17		Goldstone House	Cycle on fire exit stairs floor 8 north side locked to stair rail	Items to be removed local procedures		
18/12/17		Goldstone House	1st floor West side - child's scooter on fire exit stair well	Items to be removed local procedures		
18/12/17		Goldstone House	Outside Goldstone house fire hydrant cover has come off hinges located at entrance to the right	Estates for repair		
18/12/17		Livingstone House	Mats outside of properties floor 9	Items to be removed local procedures		
18/12/17		Livingstone House	Mats outside of properties floor 8. Also magazines on side of window shelf	Items to be removed local procedures		
18/12/17		Livingstone House	Mats outside of properties floor 7	Items to be removed local procedures		
18/12/17		Livingstone House	Mats outside of properties floor 3	Items to be removed local procedures		
18/12/17		Goldstone House	Storage Areas of Goldstone and Livingstone House items left discarded on the tops of locker	Items to be removed local procedures		