

# Estate Inspection

**Date of Inspection:** 27/9/18  
**Housing Officer:** James Smith  
**Attendee:**  
**Weather conditions:**

## QP14

Date	No	Block/ Street	Description of problem	Action taken	Job number/ reference
27/09/2018		St. John's Mount	Ninth Floor - Utility cupboard not closing properly	Reported to MEARS	9726537
		St. John's Mount	Fifth floor - exercise bike in landing of stairwell	Reported to Estates	Lauren Duckett
		St. John's Mount	Fifth and Third floors - Electrical cupboards being used to store furniture	Reported to Estates	Lauren Duckett