

# Estate Inspection

**Date of Inspection: 9/4/18**  
**Housing Officer: John Evans**  
**Attendee:**  
**Weather conditions:**

Date	No	Block	Description of problem	Action taken
09/04/2018		St John's Mount	external areas need clearing up-litter and overgrown	
09/04/2018	FL12	St John's Mount	fire signage not on wall	Estates
09/04/2018	FL12	St John's Mount	bulk-mattress, broken bed and rugs in gas cupboard	Estates
09/04/2018	FL10	St John's Mount	clothes, rug and table in gas cupboard and electric cupboard	Estates
09/04/2018	FL9	St John's Mount	fridge freezer and clothes dryer in gas cupboard	Estates
09/04/2018	FL6	St John's Mount	fire signage off wall	Estates
09/04/2018		St John's Mount	doormat	letter to tenant
09/04/2018	FL3	St John's Mount	insulation, bicycle and other rubbish in gas cupboard	Estates

