

Estate Inspection



[Area of Inspection] Queens Park 10

Date of Inspection: 16/05/2016

Neighbourhood Officer: Carla Baden

| Date | No. | Block/ Street | Description of problem | Action taken/Sent to | Job number/ reference | Re-inspection date |
|-------------|-----|-----------------|------------------------------|----------------------------|--------------------------|-----------------------|
| 16/05/2016 | | Wiltshire House | Doormat | Sent clearance letter | | 14/11/2016 |
| 16/05/82016 | | Wiltshire House | Doormat | Sent clearance letter | | 14/11/2016 |
| 16/05/2016 | | Wiltshire House | Doormat | Sent clearance letter | | 14/11/2016 |
| 16/05/2016 | | Wiltshire house | Doormat | Sent clearance letter | | 14/11/2016/ |
| 16/05/2016 | | Wiltshire House | Metal by windows | Sent job to Estates | | 14/11/2016 |
| 16/05/2016 | | Wiltshire House | Bike in electric cupboard | 7 day noticed | | 14/11/2016 |
| 16/05/2016 | | Wiltshire House | Mobility scooter | Part of project with Satti | | 14/11/2016 |
| 16/05/2016 | | Wiltshire House | Rubbish in electric cupboard | Sent job to Estates | | 14/11/2016 |
| 16/05/2016 | | Wiltshire House | Plant | Sent clearance letter | | 14/11/2016 |
| 16/05/2016 | | Wiltshire House | Items by door | Sent clearance letter | | 14/11/2016 |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

| Date | No. | Block/ Street | Description of problem | Action taken | Job number/ reference | Re-inspection date |
|-------------|------------|----------------------|-------------------------------|---------------------|----------------------------------|-------------------------------|
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

| Date | No. | Block/ Street | Description of problem | Action taken | Job number/ reference | Re-inspection date |
|------|-----|---------------|------------------------|--------------|--------------------------|-----------------------|
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

