

Estate Inspection

Date of Inspection: 2 March 2016

Neighbourhoods Officer: Karen Lord

Attendee:

Weather conditions:

| Date | No | Block/ Street | Description of problem | Action taken | Job number/ reference | Re- inspection date |
|--------|----|------------------|---|---------------|--------------------------|---------------------------|
| 02-Mar | | St James's House | Rubbish in cupboard opposite meter room | Estates | | |
| 02-Mar | | St James's House | Mattress, plant, mirror | Bulk Removals | | |
| 02-Mar | | St James's House | Inner electricity meter room needs padlock and staple | Estates | | |
| 02-Mar | | St James's House | Window opposite electricity meter room- hinge broken | Mears | | |
| 02-Mar | | St James's House | Cupboard opposite electricity meter room- shopping trolley full of bulk | NO | | |
| 02-Mar | | St James's House | North-side stairwell fire door closer needs adjusting | Estates | | |
| 02-Mar | | St James's House | Electric wheelchair on landing | NO | | |
| 02-Mar | | St James's House | Electric wheelchair on landing | NO | | |
| 02-Mar | | St James's House | Cupboard opposite electricity meter room- being used for storage | NO | | |

| | | | | | | |
|--------|--|------------------|--|---------|--|--|
| 02-Mar | | St James's House | Cardboard on landing | NO | | |
| 02-Mar | | St James's House | Meter room light out | Estates | | |
| 02-Mar | | St James's House | Window by lift- handle missing | Mears | | |
| 02-Mar | | St James's House | Hole in wall by lifts/electricity meter room | Mears | | |
| 02-Mar | | St James's House | Doormats (2) | NO | | |
| 02-Mar | | St James's House | Cupboard opposite electricity meter room- being used for storage | NO | | |
| 02-Mar | | St James's House | Inner electricity meter room - wheelchair and clothes horse | NO | | |
| 02-Mar | | St James's House | Electricity meter room- plastic storage box | NO | | |
| 02-Mar | | St James's House | Cupboard opposite electricity meter room- garden furniture | NO | | |
| 02-Mar | | St James's House | Window by lift- handle missing | Mears | | |
| 02-Mar | | St James's House | Mobility scooter on landing | NO | | |
| 02-Mar | | St James's House | Cupboard opposite electricity meter room- being used for storage | NO | | |
| 02-Mar | | St James's House | Doormat | NO | | |
| 02-Mar | | St James's House | Cupboard opposite electricity meter room- storing bike | NO | | |
| 02-Mar | | St James's House | Window over from lifts- handle missing | Mears | | |
| 02-Mar | | St James's House | Cupboard opposite electricity meter room- storing junk | NO | | |
| 02-Mar | | St James's House | Wheelchair, shoes, junk on landing | NO | | |

| | | | | | | |
|--------|--|------------------|---|----|--|--|
| 02-Mar | | St James's House | Mobility scooters on landing | NO | | |
| 02-Mar | | St James's House | North-side stairwell fire door closer needs adjusting | NO | | |
| 02-Mar | | St James's House | Inner electricity meter room- being used for storage | NO | | |