

Estate Inspection



Date of Inspection: 14/11/16

Inspection Area: Queen's Park 16

Housing Officer: Karen Lord

Attendees: None

Weather conditions: Dull and damp

Date	No	Block/ Street	Description of problem	Action taken	Job number/ reference	Re- inspection date
14/11/2016		Tyson Place	Car battery/ shelving in meter cupboard	Block letter		28-Nov
14/11/2016		Tyson Place	Doormat	Block letter		28-Nov
14/11/2016		Tyson Place	Bulk in meter cupboard	Block letter		28-Nov
14/11/2016		Tyson Place	Fridge in meter cupboard	Block letter		28-Nov
14/11/2016		Tyson Place	Paintpot in meter cupboard	Block letter		28-Nov
14/11/2016		Tyson Place	Bike/clothes airer/rubbish bag in meter cupboard	Block letter		28-Nov
14/11/2016		Tyson Place	Milk crate in meter cupboard	Block letter		28-Nov
14/11/2016		Tyson Place	Fold-up folding chair in meter cupboard	Block letter		28-Nov
14/11/2016		Tyson Place	Furniture in meter cupboard	Block letter		28-Nov
14/11/2016		Tyson Place	Doormats	Block letter		28-Nov
14/11/2016		Tyson Place	Staining	Block letter		28-Nov
14/11/2016		Tyson Place	Bike chained to railing by MED	Visitor removed it	N/A	28-Nov

