

Estate Inspection



Date of Inspection: 8.3.17 – QP7

Housing Officer: Mel Fraser

Attendee: None

Weather conditions: Very Windy

Date	No	Block/ Street	Description of problem	Action taken	Job number/ reference	Re- inspection date
8.3.17		Lennox Street	TV aerial junction box unsecured	SCCI aerials	9585244	
8.3.17		Lennox Street	Grass bank needs cutting back	City Parks		
8.3.17		Lennox Street	Porch/canopy missing	Mears		
8.3.17		Lennox Street	Porch disrepair	Mears	9585248	
8.3.17		Lennox Street	Bed fly tipped outside bin area	Estates Services		
8.3.17		Lennox Street	Fencing panel missing outside block 13-18	Mears	9585255	
8.3.17		Lennox Street	Graffiti on fence to side of 19-24	City Clean		
8.3.17		Lennox Street	Holes in ceiling outside 17/18. Tape in place. Repairs outstanding.	Mears		
8.3.17		Lennox Street	Offensive Graffiti on Wall of building to side of 19-24.	City Clean		
8.3.17		St John's Place,	Mattress dumped outside bin area	Estates Services		
8.3.17		St Johns Place	Mattress dumped outside bin area	Estates services		
8.3.17		St Johns Place	Ivy on front of building	City Parks		