

# Estate Inspection

**East Brighton (19)**

**Date of Inspection: 16<sup>th</sup> November 2017**

**Housing Officer: Trill Moss**

**Attendees: None**

Date	No.	Block/ Street	Description of problem	Action taken/Sent to	Job number/ reference	Re-inspection date
16/11/2017		Cotswold Place	OK			
16/11/2017		Cotswold Place	Washing machine dumped on ground floor	Emailed Estates Service Team		
16/11/2017		Wellsbourne	OK			
16/11/2017		Wellsbourne	Broken "For Sale" sign outside main entrance.	Emailed Estates Service Team		
16/11/2017		Wellsbourne	OK			
16/11/2017		Wellsbourne	Trades not working. Bulk on GF.	Emailed Estates Service Team		
16/11/2017		Framfield	OK			
16/11/2017		Lichfield	OK			
16/11/2017		Lichfield	Bulk on GF under stairs	Emailed Estates Service Team		
16/11/2017		Lichfield	OK			