Estate Inspection

Brighton & Hove City Council

Inspection Number:	H&S 05
Date of Inspection:	06/07/2017
Housing Officer:	Jake Woollard
Attendee:	None
Weather conditions:	Dry

Quick code	Number	Block/ Street	Description of problem	Action taken
bl		Brentwood Road	Blocks: Bulk items / rubbish on landing	Letter to tenant
bl		Brentwood Road	Blocks: Bulk items / rubbish on landing	Letter to tenant
bl		Brentwood Road	Blocks: Bulk items / rubbish on landing	Letter to tenant
BLO		Brentwood Road	Blocks: Leaking overflow	Passed to repairs
bl		Brentwood Road	Blocks: Bulk items / rubbish on landing	Letter to tenant
bl		Brentwood Road	Blocks: Bulk items / rubbish on landing	Letter to tenant
BL		Brentwood Road	Blocks: Bulk items / rubbish on landing	Letter to tenant
BL		Brentwood Road	Blocks: Bulk items / rubbish on landing	Letter to tenant
OPF		Brentwood Road	Blocks: Overgrown pathway front of block	Passed to cityparks
bl		Brentwood Road	Bags by electricity cupboard	Letter to block
bl		Brentwood Road	Door on stairs	Letter to block
MEDL		Brentwood Road	Blocks: MED lock broken	Passed to repairs
OPF		Brentwood Road	Blocks: Overgrown pathway front of block	Passed to cityparks
OPF		Brentwood Road	Blocks: Overgrown pathway front of block	Passed to cityparks
bl		Merevale	Blocks: Bulk items / rubbish on landing	Letter to tenant
bl		Merevale	Blocks: Bulk items / rubbish on landing	Letter to tenant
PLO		Merevale	Property: Leaking overflow	Passed to repairs
bl		Merevale	Blocks: Bulk items / rubbish on landing	Letter to tenant
bl		Merevale	Washing on landing	Letter to tenant

bl		Merevale	Blocks: Bulk items / rubbish on landing	Letter to tenant
bl		Merevale	Blocks: Bulk items / rubbish on landing	Letter to tenant
bl		Merevale	Blocks: Bulk items / rubbish on landing	Letter to tenant
medl		Merevale	Blocks: MED lock broken	Passed to repairs
opf		Merevale	Elder tree rooting into brickwork	Passed to cityparks
MEDL		Merevale	Blocks: MED lock broken	Passed to repairs
oth		Merevale	Tree roots causing uneven pathway leading from both blocks to road	Passed to repairs
LG		Merevale	Blocks: Litter in grounds	Passed to estates
opf		Merevale	Blocks: Overgrown pathway front of block	Passed to cityparks
opf		Merevale	Sycamore rooting from brickwork o/s 28 front	Passed to cityparks
OPB		Merevale	Blocks: Overgrown pathway back of block	Passed to cityparks