

Estate Inspection

Area of Inspection: Hangleton & Knoll 6 – Harmsworth Crescent and Aldwick Mews

Date of Inspection: 15 May 2018

Housing Officer: Eve Hitchens

Attendees: none

Date	No.	Block / Street	Description of problem	Action taken / Sent to	Job number / reference	Re-inspection date
15/05/2018		Harmsworth Crescent	There is a shower metal rack by garage	Reported to Estates		
15/05/2018		Harmsworth Crescent	By block there are some bike wheels	Reported to Estates		
15/05/2018		Harmsworth Crescent	Fire door opposite flat not closing	Reported to Estates		
15/05/2018		Harmsworth Crescent	Top of stairs to block there is a doormat	Reported to Estates		
15/05/2018		Harmsworth Crescent	Flat has a board over their front door	Emailed Repairs to find out if a replacement door is on order		
15/05/2018		Harmsworth Crescent	Generally, the area is overgrown (weeds and grass growing along edges, in between paving slabs)	Arranging for Mears to do a general tidy up		