

# Estate Inspection

**Inspection Number:** Hollingdean & Stanmer 5

**Date of Inspection:** 3<sup>rd</sup> July 2018

**Housing Officer:** Jake Woollard

**Attendee:** None

**Weather conditions:** Dry

No	Block/ Street	Description of problem	Action taken	Re-inspection date
	Merevale	Bulk on landing	Letter to resident	All re-inspection dates mid july
	Merevale	Bulk on landing	Letter to resident	
	Merevale	Bulk on landing	Letter to resident	
	Merevale	Bulk on landing	Letter to resident	
	Merevale	Bulk on landing	Letter to resident	
13-23	Merevale	MED lock broken	Passed to repairs	
14-24	Merevale	Path at front very uneven due to tree roots	Request uneven path sign from estates	
25-35	Merevale	Bike in stairwell	Letter to block	
37-47	Merevale	Broken trampoline at rear of block	Passed to estates	
	Merevale	Weedy paths throughout	Passed to estates	

No	Block/ Street	Description of problem	Action taken	Re-inspection date
10-20	Brentwood Road	Shed door off hinges rhs block	Passed to estates	
	Brentwood Road	Bulk landing	Letter to resident	
	Brentwood Road	Bulk landing	Letter to resident	
	Brentwood Road	Bulk landing	Letter to resident	
	Brentwood Road	Bulk landing	Letter to resident	
	Brentwood Road	Bulk landing	Letter to resident	
	Brentwood Road	Bulk landing	Letter to resident	
	Brentwood Road	Bulk landing	Letter to resident	



No	Block/ Street	Description of problem	Action taken	Re-inspection date